



**LU Mercedes GLA 200: GZ4708**

|                                    |                          |              |                  |
|------------------------------------|--------------------------|--------------|------------------|
| Vinnumber:                         | <b>WDC1569081J320763</b> | Versionname: | <b>d Style</b>   |
| First Registrationdate:            | <b>24/10/2016</b>        | Fiscalpower: |                  |
| Expertise Mileage:                 | <b>26042</b>             | Power Kw:    | <b>100</b>       |
| Bodytype:                          |                          | Body color:  | <b>Black</b>     |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>   |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b> |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>        |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>4524</b>      |
| Number of doors:                   | <b>5</b>                 |              |                  |
| Number of seats:                   | <b>5</b>                 |              |                  |
| Number head rests:                 | <b>5</b>                 |              |                  |
| Rims summer:                       | <b>Aluminium</b>         |              |                  |
| Category:                          | <b>Passenger Car</b>     |              |                  |
| Oil level:                         | <b>OK</b>                |              |                  |
| Registration Certificate Car (BE): | <b>No</b>                |              |                  |

**Options**

|                                |                                  |                       |
|--------------------------------|----------------------------------|-----------------------|
| Radio CD                       |                                  | Central consol F      |
| GPS storage                    |                                  | Luggage cover         |
| GPS storage                    | <b>SD</b>                        | Front parking sensors |
| Windows electric F             |                                  | Rear parking sensors  |
| Windows electric R             |                                  |                       |
| Cruise Control                 |                                  |                       |
| Steering wheel multifunctional |                                  |                       |
| Seats F heated                 |                                  |                       |
| Radio multimedia               |                                  |                       |
| Type of headlighting           | <b>Headlighting Xenon</b>        |                       |
| Type of GPS                    | <b>GPS big screen color</b>      |                       |
| Type of Lining                 | <b>Lining artificial leather</b> |                       |
| Type of climate control        | <b>Autom climate control</b>     |                       |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>215/60/17/96 V LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 6 mm</b> | Fr.R. | <b>Michelin: 6 mm</b> |
|                                  | Re.L. | <b>Michelin: 6 mm</b> | Re.R. | <b>Michelin: 6 mm</b> |

**Assistance equipment**

|            |            |            |            |
|------------|------------|------------|------------|
| Repair kit | <b>Yes</b> | Compressor | <b>Yes</b> |
|------------|------------|------------|------------|

|  |               |
|--|---------------|
| Total cost ex VAT                              | <b>487,35</b> |
| Certificate Of Conformity, Missing, Acceptable | <b>0,00</b>   |



|  |             |
|--|-------------|
| Bumper moulding B. Deformed / Strained. Acceptable | <b>0,00</b> |
|--|-------------|

Bumper moulding R, Deformed / Strained, Acceptable

0,00

No pictures to display

Bodywork, Dirty, Cleaning

25,00



Door F R, Dent(s), LI - Repair and paint (complete)

462,35

