



**MERCEDES GLC COUPE: 1RSE749**

Vinnumber:	<b>WDC2533091F236267</b>	Versionname:	<b>GLC 250 d 4MATIC</b>
First Registrationdate:	<b>16/02/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>46956</b>	Power Kw:	<b>150</b>
Bodytype:		Body color:	<b>Brown</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>4 Weel</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>3607</b>
Maintenance:	<b>IN 116 DAGEN SERVICE B</b>		
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats F L ventilated	
GPS storage	<b>HD</b>	Seats F R ventilated	
GPS storage		Sun Roof electric	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Cruise Control		Front parking sensors	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated			
Type of headlighting	<b>Headlighting Xenon</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**


Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/55/19/105 V LightMetal</b>				
Winter tyres:	Fr.L.	<b>Michelin: 8 mm</b>	Fr.R.	<b>Michelin: 8 mm</b>
	Re.L.	<b>Michelin: 4 mm</b>	Re.R.	<b>Michelin: 4 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>961,46</b>
Bonnet, Chemical polution, LI - Repair and paint (complete)			<b>348,09</b>



Alloy rim F L polished, Scratch(es), Acceptable 0,00

No pictures to display

Wing F L, Chemical polution, LI - Repair and paint (complete) 264,21



Windscreen, Crack, E - Replace 0,00



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Maintenance, Maintenance, Acceptable 0,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 254,16

