



**TOYOTA YARIS: CX7616**

Vinnumber:	<b>VNKKD3D370A263669</b>	Versionname:	<b>1.5 VVT-I HYBRID DYNAMIC AUTO</b>
First Registrationdate:	<b>22/07/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>31364</b>	Power Kw:	<b>74</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4631</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
GPS storage			
Windows electric F			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>175/65/15/84 H LightMetal</b>			
Summer tyres:	Fr.L.	<b>Dunlop: 6 mm</b>	Fr.R.	<b>Dunlop: 6 mm</b>
	Re.L.	<b>Dunlop: 7 mm</b>	Re.R.	<b>Dunlop: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT 1725,10

Bonnet, Chemical polution, LI - Repair and paint (complete) 232,06





Bumper F, Scratch(es), LI - Repair and paint (complete) 169,44



Interior, Dirty, Cleaning 100,00



Bumper F M, Broken, Smart repair 110,64



Bodywork, Glue residues, Remove lettering 0,00

No pictures to display

Bumper R, Broken, Le - Replace and paint 535,20



Door F L, Dent(s), PDR - Paintless dent repair 82,80



Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete) 248,80



Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	246,56
---	--------

