



RENAULT Trafic: 1EVQ106

Vinnnumber:	VF1FLA0AEDY490971	Versionname:	TRAFIC 27 B/F L1H1 Gr.Conf.FAP(E5)90PK
First Registrationdate:	2/04/2013	Fiscalpower:	
Expertise Mileage:	72755	Power Kw:	66
Bodytype:	Transporter	Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3511
Number of doors:	5		
Number of seats:	3		
Number head rests:	3		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Radio multimedia	Type of Tow bar
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control
	Tow bar fixed

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/65/16/107 T Steel				
Summer tyres:	Fr.L.	Semperit: 7 mm	Fr.R.	Semperit: 7 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT 2724,16

Interior, Dirty, Shampooing 100,00





Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Bumper R, Crack, E - Replace

329,40



Ignition key, Missing, E - Replace

150,00

No pictures to display

Blinker F R, Broken, E - Replace

35,25



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

165,13



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

238,76



Door moulding Lower F L, Missing, E - Replace

91,50



Door moulding Lower F R, Missing, E - Replace

91,50



Trunk door R L, Dent(s) and scratch(es), It - Spot repair

115,56



Central pillar R, Dent(s) and scratch(es), LI - Repair and paint (complete)

366,49



Bodywork, Glue residues, Remove lettering

0,00

No pictures to display

Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete) 232,88



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 231,15



Wheel covers (all), Scratch(es), E - Replace 25,00



Bumper corner R L, Scratch(es), Smart repair 110,64



Door moulding Lower R R, Missing, E - Replace 91,50



Dashboard, Glue residues, Smart repair 110,64

