



**TOYOTA AURIS: YX7350**

Vinnumber:	<b>SB1MS3JE90E301607</b>	Versionname:	<b>1.8 HYBRID DESIGN NAV BUSINESS AUTO</b>
First Registrationdate:	<b>12/01/2017</b>	Fiscalpower:	
Expertise Mileage:	<b>37379</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Berline</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3629</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>205/55/16/91 V LightMetal</b>				
Summer tyres:	Fr.L.	<b>Continental: 5 mm</b>	Fr.R.	<b>Continental: 5 mm</b>
	Re.L.	<b>Continental: 7 mm</b>	Re.R.	<b>Continental: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>2378,93</b>
Window R L door, Scratch(es), Acceptable			<b>0,00</b>
<i>No pictures to display</i>			
Bumper R, Dent(s) and scratch(es), Le - Replace and paint			<b>651,00</b>



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

50,00



Protection plate M, Tear, E - Replace

64,40



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00





Alloy rim F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Door F L, Scratch(es), Acceptable 0,00

*No pictures to display*

Bumper F, Dent(s) and scratch(es), Le - Replace and paint 735,00



Certificate Of Conformity, Missing, E - Replace 150,00

*No pictures to display*

Door F R, Dent(s), Acceptable 0,00

*No pictures to display*

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18

