


VOLVO V40: 1GAL690

Vinnumber:	VV1MV848BE2121960	Versionname:	V40 D2 Base Powershift 115PK Aut.
First Registrationdate:	6/12/2013	Fiscalpower:	
Expertise Mileage:	116900	Power Kw:	84
Bodytype:		Body color	Blue
Gearbox:	Automatic	Paint type	Metallic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3433
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Panoramic roof	
GPS storage	HD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	Tow bar removable
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/50/17/93 V LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Continental: 3 mm	Re.R.	Continental: 3 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			839,96
Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)			95,00



Bumper corner R R, Deformed / Strained, Smart repair

110,64



Alloy rim R L polished, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Bad repair, LI - Repair and paint (complete)

308,20



Bumper F L, Scratch(es), It - Spot repair

115,56



Bumper corner R L, Scratch(es), It - Spot repair

115,56



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)

95,00

