



AUDI A3: 1FUZ829

Vinnumber:	WAUZZZ8V6EA080081	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	4/11/2013	Fiscalpower:	
Expertise Mileage:	80920	Power Kw:	77
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	3129
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 H LightMetal				
Winter tyres:	Fr.L.	Continental: 6 mm	Fr.R.	Continental: 6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2909,65
-------------------	---------

Roof pillar L, Hail damage, PDR - Hail	75,00
--	-------



Roof pillar R, Hail damage, PDR - Hail

75,00



Bumper corner R R, Dent(s) and scratch(es), It - Spot repair

115,56



Tailgate, Hail damage, PDR - Hail

250,00



Interior, Stain, Cleaning

0,00

No pictures to display

Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R R, Dent(s), Acceptable

0,00

No pictures to display

Bonnet, Hail damage, Le - Replace and paint

1016,70



Roof, Hail damage, LI - Repair and paint (complete)

481,50



Alloy rim F R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Mirror side blinker R, Broken, E - Replace 30,00



Alloy rim F L, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 211,80



Door R L, Bad repair, LI - Repair and paint (complete) 318,35

No pictures to display

Maintenance, Maintenance, Execute 0,00

No pictures to display