



**AUDI A4 AVANT: 1KCD257**

Vinnumber:	<b>WAUZZZ8K4FA112324</b>	Versionname:	<b>2.0 TDI ULTRA 100KW</b>
First Registrationdate:	<b>30/03/2015</b>	Fiscalpower:	
Expertise Mileage:	<b>175660</b>	Power Kw:	<b>100</b>
Bodytype:	<b>Break</b>	Body color:	<b>Dark Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>2503</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>Tow bar fixed</b>
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/95 W LightMetal</b>			
Summer tyres:	Fr.L.	<b>Goodyear: 3 mm</b>	Fr.R.	<b>Goodyear: 3 mm</b>
	Re.L.	<b>Goodyear: 4 mm</b>	Re.R.	<b>Goodyear: 4 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>423,60</b>
-------------------	---------------

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	<b>211,80</b>
---	---------------





Bonnet, Stone chip(s), Acceptable	0,00
-----------------------------------	------

*No pictures to display*

Rear window, Scratch(es), Acceptable	0,00
--------------------------------------	------

*No pictures to display*

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	--------

