



**MERCEDES Vito: 1DIB449**

|                         |                                 |              |                              |
|-------------------------|---------------------------------|--------------|------------------------------|
| Vinnumber:              | <b>WDF63960113739597</b>        | Versionname: | <b>VITO 110 B/F SWB 95PK</b> |
| First Registrationdate: | <b>23/05/2012</b>               | Fiscalpower: |                              |
| Expertise Mileage:      | <b>177131</b>                   | Power Kw:    | <b>70</b>                    |
| Bodytype:               | <b>Transporter</b>              | Body color:  | <b>Red</b>                   |
| Gearbox:                | <b>MAN 6 VIT</b>                | Paint type:  | <b>Opaque</b>                |
| Transmission:           | <b>Front</b>                    | Rims summer: | <b>Steel</b>                 |
| Fueltype:               | <b>Diesel</b>                   | Oil level:   | <b>OK</b>                    |
| Battery functioning:    | <b>Yes</b>                      | Parking lot: | <b>2619</b>                  |
| Number of doors:        | <b>5</b>                        |              |                              |
| Number of seats:        | <b>2</b>                        |              |                              |
| Number head rests:      | <b>2</b>                        |              |                              |
| Rims summer:            | <b>Steel</b>                    |              |                              |
| Category:               | <b>Light Commercial Vehicle</b> |              |                              |
| Oil level:              | <b>OK</b>                       |              |                              |

**Options**

|                         |                                  |                       |                   |
|-------------------------|----------------------------------|-----------------------|-------------------|
| Radio CD                |                                  | Front parking sensors |                   |
| Windows electric F      |                                  | Rear parking sensors  |                   |
| Type of headlighting    | <b>Headlighting Halogen</b>      | Type of Tow bar       | <b>No Tow bar</b> |
| Type of GPS             | <b>No GPS</b>                    |                       |                   |
| Type of Lining          | <b>Lining artificial leather</b> |                       |                   |
| Type of climate control | <b>Manual climate control</b>    |                       |                   |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|               |                              |                       |       |                       |
|---------------|------------------------------|-----------------------|-------|-----------------------|
|               | <b>195/65/16/105 T Steel</b> |                       |       |                       |
| Summer tyres: | Fr.L.                        | <b>Michelin: 4 mm</b> | Fr.R. | <b>Michelin: 4 mm</b> |
|               | Re.L.                        | <b>Michelin: 5 mm</b> | Re.R. | <b>Michelin: 5 mm</b> |

**Assistance equipment**

|   |        |
|---|--------|
| Total cost ex VAT                       | 260,64 |
| Bodywork, Not original part, Acceptable | 0,00   |
| <i>No pictures to display</i>           |        |
| Bumper R, Dent(s), Smart repair         | 110,64 |



|  |        |
|--|--------|
| Sidewall RL (LCV), Scratch(es), Acceptable | 0,00   |
| <i>No pictures to display</i>              |        |
| Ignition key, Missing, E - Replace         | 150,00 |

No pictures to display

|                                   |      |
|-----------------------------------|------|
| Bumper F, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

|                                 |      |
|---------------------------------|------|
| Bonnet, Scratch(es), Acceptable | 0,00 |
|---------------------------------|------|

No pictures to display