



**LU Mercedes GLA 200: GZ4710**

Vinnumber:	<b>WDC1569081J320569</b>	Versionname:	<b>d Style</b>
First Registrationdate:	<b>24/10/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>56776</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Black</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>4630</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>SD</b>	Luggage cover
GPS storage		Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	<b>Headlighting Xenon</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>215/60/17/100 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Michelin: 5 mm</b>	Fr.R.	<b>Michelin: 5 mm</b>
	Re.L.	<b>Michelin: 7 mm</b>	Re.R.	<b>Michelin: 7 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>674,89</b>
Certificate Of Conformity, Missing, Acceptable			<b>0,00</b>



Bumper moulding F, Dent(s) and scratch(es), Smart repair 110,04



Bumper spoiler F, Broken, E - Replace 158,04



Maintenance, Maintenance, Execute 0,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Bodywork, Chemical polution, Chemical cleaning 25,00



Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Wing moulding F L, Broken, E - Replace 84,78



Wheel arch cover F L, Broken, E - Replace 84,63



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80



Door R R, Dent(s), Acceptable 0,00

No pictures to display

Tyre F L, Out of tolerance, P - Check 0,00



Wing R R, Dent(s) and scratch(es), Acceptable 0,00

No pictures to display