



**VOLKSWAGEN TIGUAN: 1HRE480**

Vinnumber:	<b>WVGZZZ5NZFW026544</b>	Versionname:	<b>TIGUAN Sport&amp;Style BM Tech.140PK</b>
First Registrationdate:	<b>11/09/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>134183</b>	Power Kw:	<b>103</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>4826</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD		Seats electric F L	
GPS storage	<b>HD</b>	Sun Roof electric	
GPS storage		Panoramic roof	
Windows electric F		Central consol F	
Windows electric R		Luggage cover	
Steering wheel multifunctional		Type of Tow bar	<b>No Tow bar</b>
Seats F heated			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>


**Degree of wear**

<b>215/60/17/96 H LightMetal</b>				
Summer tyres:	Fr.L.	<b>Uniroyal: 6 mm</b>	Fr.R.	<b>Uniroyal: 6 mm</b>
	Re.L.	<b>Uniroyal: 8 mm</b>	Re.R.	<b>Uniroyal: 8 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>1023,63</b>
Bonnet, Chemical polution, LI - Repair and paint (complete)	<b>290,08</b>



Bumper R, Dent(s) and scratch(es), E - Replace 415,20



Rear window, Scratch(es), E - Replace 0,00



Bumper corner R L, Scratch(es), Acceptable 0,00

No pictures to display

Backrest cover F L, Worn, Acceptable 0,00



Wing R L, Scratch(es), 67 - Polish 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Windscreen, Scratch(es), E - Replace 0,00



Door F R, Scratch(es), LI - Repair and paint (complete) 318,35

