



PEUGEOT 3008: 1C4C999

Vinnumber:	VF30U9HR8BS258910	Versionname:	3008 Confort Pack FAP 112PK
First Registrationdate:	3/10/2011	Fiscalpower:	
Expertise Mileage:	148036	Power Kw:	82
Bodytype:	Hatchback	Body color:	Silver
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3306
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		

Options

Radio CD	Central consol F
Windows electric F	Luggage cover
Cruise Control	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	No GPS
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/50/17/98 H Steel			
Winter tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			30,00
Bumper F, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Wing R R, Repaired, Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Tailgate, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			

