



MERCEDES A: 1KXL863

Vinnumber:	WDD1760121V082462	Versionname:	1.5 A 180 CDI
First Registrationdate:	24/07/2015	Fiscalpower:	
Expertise Mileage:	114810	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3109
Maintenance:	IN 37 DAGEN		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	NOT OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/95 V Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	782,26
Door R L, Scratch(es), LI - Repair and paint (complete)	318,35



Maintenance, Maintenance, P - Check 0,00

No pictures to display 115,56



Bumper corner R L, Scratch(es), It - Spot repair 30,00



Wheel cover F R, Scratch(es), E - Replace 0,00



Rear window, Not original part, Remove lettering 318,35



Door F L, Scratch(es), LI - Repair and paint (complete)