



CITROËN C4 Aircross: 1JEB240

Vinnumber:	VF7BU9HD8FZ901853	Versionname:	C4 AIRCROSS 2WD Seduction 115PK
First Registrationdate:	21/11/2014	Fiscalpower:	
Expertise Mileage:	75821	Power Kw:	84
Bodytype:		Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3631
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Panoramic roof	
GPS storage		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	215/70/16/104 H LightMetal			
Winter tyres:	Fr.L.	Michelin: 6 mm	Fr.R.	Michelin: 6 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			521,20
Rocker panel inner F L, Dent(s), Acceptable			0,00
<i>No pictures to display</i>			
Window R L door, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Alloy rim F L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door F L, Scratch(es), Acceptable			0,00

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R R, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Rocker panel inner R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Roof, Scratch(es), Acceptable	0,00
-------------------------------	------

No pictures to display

Rocker panel inner F R, Dent(s), LI - Repair and paint (complete)	115,56
---	--------



Bonnet, Chemical polution, LI - Repair and paint (complete)	290,08
---	--------

