


BMW 3: 1GHX545

Vinnumber:	WBA3D11020J626260	Versionname:	3 BER 318d 136PK
First Registrationdate:	12/02/2014	Fiscalpower:	
Expertise Mileage:	117867	Power Kw:	100
Bodytype:	Berline	Body color:	Brown
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	OK	Parking lot:	2313
Maintenance	OVER 700KM		
Battery functioning	Yes		
Number of doors	4		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	Headlighting Xenon	
Type of GPS	No GPS	
Type of Lining	Lining fabrics	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	205/60/16/96 W Steel			
Summer tyres:	Fr.L.	Kleber: 7 mm	Fr.R.	Kleber: 7 mm
	Re.L.	Kleber: 6 mm	Re.R.	Kleber: 6 mm


Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			388,80
Bumper R, Scratch(es), Acceptable			0,00



Wing R L, Dent(s), PDR - Paintless dent repair

102,60



Wheel cover F R, Scratch(es), E - Replace

30,00



Door R R, Dent(s), Acceptable

0,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Wheel cover R R, Scratch(es), E - Replace

30,00



Rearview mirror housing R, Scratch(es), Smart repair

110,64

