



**TOYOTA AYGO: RR7745**

Vinnumber:	<b>JTDKGNEC60N161816</b>	Versionname:	<b>1.0 VVT-I X-PLAY MMT</b>
First Registrationdate:	<b>13/04/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>14798</b>	Power Kw:	<b>51</b>
Bodytype:		Body color	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer	<b>Steel</b>
Fueltype:	<b>Petrol</b>	Oil level	<b>OK</b>
Maintenance	<b>OK</b>	Parking lot	<b>4711</b>
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>4</b>		
Number head rests	<b>4</b>		
Rims summer	<b>Steel</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

GPS storage		Luggage cover	
GPS storage	<b>HD</b>	Type of Tow bar	<b>No Tow bar</b>
Windows electric F			
Steering wheel multifunctional			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>165/60/15/77 H Steel</b>				
Summer tyres:	Fr.L.	<b>Continental: 6 mm</b>	Fr.R.	<b>Continental: 6 mm</b>
	Re.L.	<b>Continental: 6 mm</b>	Re.R.	<b>Continental: 6 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
------------	------------	------------	------------

Total cost ex VAT	<b>650,76</b>
-------------------	---------------

Wheel cover F R, Scratch(es), Acceptable	<b>0,00</b>
--	-------------

*No pictures to display*

Interior, Dirty, Acceptable	<b>0,00</b>
-----------------------------	-------------



Ignition key, Missing, E - Replace

150,00



Bonnet, Chemical polution, Acceptable

0,00

*No pictures to display*

Roof, Chemical polution, LI - Repair and paint (complete)

385,20



Bumper F R, Scratch(es), It - Spot repair

115,56

