



VOLKSWAGEN Caddy: 1JEE687

Vinnumber:	WV2ZZZ2KZFX058164	Versionname:	D
First Registrationdate:	24/11/2014	Fiscalpower:	
Expertise Mileage:	166804	Power Kw:	75
Bodytype:		Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2809
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Light Commercial Vehicle		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD	Central consol F
Windows electric F	Rear parking sensors
Cruise Control	
Type of headlighting	Headlighting Halogen
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/94 H Steel			
Summer tyres:	Fr.L. Michelin: 5 mm	Fr.R. Michelin: 5 mm	
	Re.L. Firestone: 4 mm	Re.R. Firestone: 4 mm	

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1962,66
-------------------	----------------

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)	115,56
--	---------------



Internal Boot Lining R, Scratch(es), Smart repair	0,00
---	-------------



Wheel cover F R, Broken, E - Replace

30,00



Storage compartment housing, Scratch(es), E - Replace

93,20



Headlight L, Scratch(es), E - Replace

396,00



Door F L, Scratch(es), 67 - Polish

0,00



Bodywork, Damaged, Acceptable

0,00



Bumper R, Scratch(es), E - Replace

415,20



Wing R L, Scratch(es), 67 - Polish

0,00



Trunk lid covering R, Hole, E - Replace

25,00



Internal Boot Lining L, Scratch(es), Smart repair

0,00



Sill outer R, Dent(s), LI - Repair and paint (complete)

358,50



Wheel cover F L, Scratch(es), E - Replace

30,00



Bumper F, Scratch(es), E - Replace

499,20



Door R L, Scratch(es), 67 - Polish

0,00

