



VOLKSWAGEN GOLF VII: AB0563

Vinnumber:	WVWZZZAUZFP088827	Versionname:	1.6 TDI 77KW DSG BMT HIGHLINE
First Registrationdate:	21/03/2015	Fiscalpower:	
Expertise Mileage:	128715	Power Kw:	77
Bodytype:	Hatchback	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3308
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/17/91 H LightMetal				
Winter tyres:	Fr.L.	Michelin: 1,6 mm	Fr.R.	Michelin: 1,6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	1546,91
-------------------	----------------

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	211,80
---	---------------



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Door F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (complete) 318,35



Certificate Of Conformity, Missing, E - Replace 150,00

No pictures to display

Wing R R, Chemical polution, Acceptable 0,00



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete) 308,20



Sill outer R, Dent(s), PDR - Paintless dent repair 63,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete) 115,56



Alloy Rims (all), Scratch(es), LI - Repair and paint (complete) 380,00





Door R R, Scratch(es), Acceptable

0,00

No pictures to display