



TOYOTA Auris: 1FWM320

| | | | |
|------------------------------------|--------------------------|--------------|------------------------------------------------|
| Vinnumber: | SB1MS3JE80E056895 | Versionname: | AURIS BER HSD Hybr.Lounge CVT 99PK Aut. |
| First Registrationdate: | 19/11/2013 | Fiscalpower: | |
| Expertise Mileage: | 60170 | Power Kw: | 73 |
| Bodytype: | | Body color: | White |
| Gearbox: | Automatic | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Hybrid Petrol | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3205 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|--------------------------------|---------------------------------------|-----------------------|-------------------|
| Radio CD | | Panoramic roof | |
| GPS storage | HD | Central consol F | |
| GPS storage | | Luggage cover | |
| Windows electric F | | Front parking sensors | |
| Windows electric R | | Rear parking sensors | |
| Cruise Control | | Type of Tow bar | No Tow bar |
| Steering wheel multifunctional | | | |
| Seats F heated | | | |
| Alarm | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining semi-artificial leather | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|---------------------|-------|---------------------|
| 225/45/17/91 W LightMetal | | | | |
| Summer tyres: | Fr.L. | Dunlop: 4 mm | Fr.R. | Dunlop: 4 mm |
| | Re.L. | Dunlop: 0 mm | Re.R. | Dunlop: 0 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| | | Jack | Yes |

| | |
|-------------------|--------|
| Total cost ex VAT | 728,88 |
|-------------------|--------|

| | |
|-----------------------------------|------|
| Door R R, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

| | |
|-----------------------------------|------|
| Door R L, Scratch(es), Acceptable | 0,00 |
|-----------------------------------|------|

No pictures to display

Bumper F, Scratch(es), Acceptable

0,00

No pictures to display

Alloy Rims (all), Scratch(es), LI - Repair and paint (complete)

380,00



Windscreen, Stone chip(s), Windscreen repair

58,80



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Tailgate, Scratch(es), Acceptable

0,00

No pictures to display