



VOLVO V60 CROSS COUNTRY: 1PAG332

Vinnumber:	YV1FZARC1H1023400	Versionname:	2.0 D3 SUMMUM
First Registrationdate:	20/05/2016	Fiscalpower:	
Expertise Mileage:	157336	Power Kw:	110
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3728
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats R heated	
GPS storage	HD	Seats electric F L	
GPS storage		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

235/50/18/101 W LightMetal				
Summer tyres:	Fr.L.	Michelin: 1,6 mm	Fr.R.	Michelin: 1,6 mm
	Re.L.	Michelin: 5 mm	Re.R.	Michelin: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	211,80
-------------------	---------------

Sill outer R, Scratch(es), Acceptable	0,00
---------------------------------------	-------------

No pictures to display

Bumper F, Bad repair, LI - Repair and paint (complete)	211,80
--	---------------

