



VOLVO V60: 1JAU279

Vinnumber:	VV1FW8481F1246407	Versionname:	V60 BRE D2 Kinetic 115PK
First Registrationdate:	19/11/2014	Fiscalpower:	
Expertise Mileage:	71615	Power Kw:	84
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3230
Maintenance:	BINNEN 156 KM		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/60/16/96 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 4 mm	Re.R.	Michelin: 4 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1142,88
Outer door handle R R, Scratch(es), LI - Repair and paint (complete)			115,56



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

380,20



Floor covering F L, Tear, E - Replace

252,00



Alloy rim R L, Scratch(es), Acceptable

0,00



Alloy rim R R, Scratch(es), Acceptable

0,00



Door panel F L, Tear, E - Replace

114,00



Bumper F, Scratch(es), It - Spot repair

115,56



Door F L, Dent(s), It - Spot repair

115,56



Bumper R, Scratch(es), Acceptable

0,00

No pictures to display

Door R L, Dent(s) and scratch(es), Acceptable

0,00



Door F R, Dent(s), Acceptable

0,00



Interior, Dirty, Cleaning

25,00



Bodywork, Dirty, Cleaning

25,00



Wing F L, Scratch(es), 67 - Polish

0,00



Alloy rim F R, Scratch(es), Acceptable

0,00



Door F L, Scratch(es), 67 - Polish

0,00

