


**BMW 3: 1GTE170**

Vinnumber:	<b>WBA3K110X0F829700</b>	Versionname:	<b>3 TOURING 318d 136PK</b>
First Registrationdate:	<b>23/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>112216</b>	Power Kw:	<b>100</b>
Bodytype:		Body color:	<b>Grey</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metallic</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance	<b>1/10/2018</b>	Parking lot:	<b>3532</b>
Maintenance	<b>NOT OK</b>		
Battery functioning	<b>Yes</b>		
Number of doors	<b>5</b>		
Number of seats	<b>5</b>		
Number head rests	<b>5</b>		
Rims summer	<b>Aluminium</b>		
Category	<b>Passenger Car</b>		
Oil level	<b>OK</b>		
Registration Certificate Car (BE)	<b>Yes</b>		

**Options**

Radio CD		Central consol F
GPS storage	<b>HD</b>	Luggage cover
GPS storage		Rear parking sensors
Windows electric F		
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

	<b>205/60/16/92 H LightMetal</b>			
Winter tyres:	Fr.L.	<b>Goodyear: 6 mm</b>	Fr.R.	<b>Goodyear: 5 mm</b>
	Re.L.	<b>Goodyear: 5 mm</b>	Re.R.	<b>Goodyear: 5 mm</b>

**Assistance equipment**

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
		Runflat	<b>Yes</b>

Total cost ex VAT		<b>765,60</b>
Maintenance, Maintenance, Execute		<b>0,00</b>



Seat cover F L, Worn, Acceptable	0,00
----------------------------------	------

No pictures to display

Wing F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)	307,80
---	--------



Ignition key, Missing, E - Replace	150,00
------------------------------------	--------



Door panel R L, Scratch(es), Acceptable	0,00
---	------

No pictures to display

Alloy rim R L, Scratch(es), Acceptable	0,00
--	------

No pictures to display

Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)	307,80
---	--------

