



AUDI A1 SPORTBACK: 1RAJ203

| | | | |
|------------------------------------|--------------------------|--------------|---------------------|
| Vinnumber: | WAUZZZ8X9HB036995 | Versionname: | 1.4 TDI 66kW |
| First Registrationdate: | 26/10/2016 | Fiscalpower: | |
| Expertise Mileage: | 33498 | Power Kw: | 66 |
| Bodytype: | | Body color: | Blue |
| Gearbox: | MAN 5 VIT | Paint type: | Metalic |
| Transmission: | Front | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 1210 |
| Number of doors: | 5 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | | | |
|-------------------------|------------------------------|----------------------|-------------------|
| Radio CD | | Luggage cover | |
| GPS storage | | Rear parking sensors | |
| GPS storage | SD | Type of Tow bar | No Tow bar |
| Windows electric F | | | |
| Windows electric R | | | |
| Cruise Control | | | |
| Radio multimedia | | | |
| Type of headlighting | Headlighting Halogen | | |
| Type of GPS | GPS big screen color | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Autom climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|----------------------------------|-------|---------------------|-------|---------------------|
| 185/60/15/84 H LightMetal | | | | |
| Summer tyres: | Fr.L. | Dunlop: 6 mm | Fr.R. | Dunlop: 6 mm |
| | Re.L. | Dunlop: 7 mm | Re.R. | Dunlop: 7 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
| | | Jack | Yes |

| | |
|---|--------|
| Total cost ex VAT | 866,74 |
| Bonnet, Chemical polution, LI - Repair and paint (complete) | 232,06 |



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display


Wing R L, Chemical polution, It - Spot repair 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper R, Scratch(es), LI - Repair and paint (complete) 169,44



Door R L, Chemical polution, LI - Repair and paint (complete) 254,68

