



AUDI A3: 1FON246			
Vinnumber:	WAUZZZ8V2EA051581	Versionname:	A3 SB Attraction 105PK
First Registrationdate:	6/09/2013	Fiscalpower:	
Expertise Mileage:	144595	Power Kw:	77
Bodytype:	Berline	Body color:	.
Gearbox:	MAN 6 VIT	Body color:	Grey
Transmission:	Front	Paint type:	Metalic
Fueltype:	Diesel	Rims summer:	Aluminium
Battery functioning:	Yes	Oil level:	OK
Number of doors:	5	Parking lot:	1110
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Sun Roof electric	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		
Level control			

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
	205/55/16/91 V LightMetal			
Summer tyres:	Fr.L.	Goodyear: 5 mm	Fr.R.	Goodyear: 5 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Number of charging cables (normal)	0		
Number of charging cables (rapid charge)	0		

Total cost ex VAT	2098,38
Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	462,35



Wing F L, Scratch(es), Acceptable 0,00



Outer door handle F R, Scratch(es), LI - Repair and paint (complete) 115,56



Wheel aperture R R, Scratch(es), Acceptable 0,00



Door F L, Dent(s), LI - Repair and paint (complete) 366,35



Wing R R, Scratch(es), LI - Repair and paint (complete) 308,20



Wing R L, Scratch(es), It - Spot repair 115,56



Alloy rim F R, Scratch(es), LI - Repair and paint (complete) 95,00



Outer door handle F L, Scratch(es), LI - Repair and paint (complete) 115,56



Ignition key, Missing, E - Replace 150,00



Door R L, Dent(s), PDR - Paintless dent repair 63,00



Bumper R, Deformed / Strained, LI - Repair and paint (complete) 0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Bumper F, Scratch(es), LI - Repair and paint (complete) 211,80

