



MERCEDES B180: 1FNT388

Vinnumber:	WDD2462121J193456	Versionname:	B 180 CDI BE 109PK
First Registrationdate:	2/09/2013	Fiscalpower:	
Expertise Mileage:	50220	Power Kw:	80
Bodytype:		Body color:	Grey
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance	PLUS 152 D	Parking lot:	3128
Maintenance	OK		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

195/65/15/91 T Steel				
Summer tyres:	Fr.L.	Michelin: 4 mm	Fr.R.	Michelin: 4 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	No	Compressor	Yes
------------	-----------	------------	------------

Total cost ex VAT	1450,71
-------------------	----------------

Bumper R, Dent(s), LI - Repair and paint (complete)	259,80
---	---------------



Tailgate, Scratch(es), Acceptable

0,00



Tyre repair kit, Missing, E - Replace

210,53



Windscreen, Repaired, P - Check

0,00



Window F L door, Scratch(es), 67 - Polish

0,00



Sill outer R, Scratch(es), LI - Repair and paint (complete)

310,50



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Wheel cover F R, Scratch(es), E - Replace

30,00



Wheel cover R L, Scratch(es), E - Replace

30,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

259,80



Window R L door, Scratch(es), 67 - Polish

0,00



Wheel cover R R, Scratch(es), E - Replace

30,00



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Wheel cover F L, Scratch(es), E - Replace

30,00



Ignition key, Missing, Acceptable

0,00

