


BMW X5: 1GCS491

Vinnumber:	WBAKS410X00C35854	Versionname:	X5 3.0dA xDrive30 258PK Aut.
First Registrationdate:	2/01/2014	Fiscalpower:	
Expertise Mileage:	194613	Power Kw:	190
Bodytype:		Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	4 Weel	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3406
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F
GPS storage		Luggage cover
GPS storage	HD	Front parking sensors
Windows electric F		Rear parking sensors
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Seats F heated		
Radio multimedia		
Type of headlighting	Headlighting Xenon	
Type of GPS	GPS big screen color	
Type of Lining	Lining leather	
Type of climate control	Autom climate control	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	225/55/18/109 W LightMetal			
Summer tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 4 mm	Re.R.	Pirelli: 4 mm

Assistance equipment

Repair kit	No	Compressor	No
Total cost ex VAT			795,24
Bumper corner R L, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Door R R, Scratch(es), Acceptable			0,00

No pictures to display

Compressor, Missing, E - Replace 0,00

No pictures to display

Mirror side blinker L, Scratch(es), E - Replace 31,20



Door R L, Scratch(es), LI - Repair and paint (complete) 382,02



Bumper corner R R, Scratch(es), Acceptable 0,00

No pictures to display

Wing F R, Scratch(es), It - Spot repair 0,00



Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 382,02

