



AUDI A4: 1GRR535

Vinnumber:	WAUZZZ8K5EA114937	Versionname:	A4 BER TDie 136PK
First Registrationdate:	10/04/2014	Fiscalpower:	
Expertise Mileage:	85323	Power Kw:	100
Bodytype:		Body color:	Blue
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2625
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	DVD	Rear parking sensors	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK


Degree of wear

205/60/16/96 H LightMetal				
Winter tyres:	Fr.L.	BF Goodrich: 5 mm	Fr.R.	BF Goodrich: 5 mm
	Re.L.	BF Goodrich: 6 mm	Re.R.	BF Goodrich: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	2026,76
Roof, Hail damage, PDR - Paintless dent repair	221,40



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bodywork, Damaged, Acceptable

0,00

No pictures to display

Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Wing F L, Scratch(es), LI - Repair and paint (complete)


220,18



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08





Sill outer L, Dent(s) and scratch(es), LI - Repair and paint (complete)

310,50



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (partial)

250,00



Tailgate, Dent(s), PDR - Paintless dent repair

82,80



Interior, Damaged, Acceptable

0,00

No pictures to display

Door R L, Scratch(es), LI - Repair and paint (partial)

250,00

