


BMW 4 Gran Coupe: 1HHY163

Vinnumber:	WBA4D51080D424176	Versionname:	4 GRAN COUPE 418d 136PK
First Registrationdate:	29/07/2014	Fiscalpower:	
Expertise Mileage:	123196	Power Kw:	100
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OVER 2200 KM	Parking lot:	2714
Maintenance:	OK		
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Alarm			
Type of headlighting	Headlighting Xenon		
Type of GPS	No GPS		
Type of Lining	Lining artificial leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/50/17/94 W LightMetal				
Summer tyres:	Fr.L.	Continental: 8 mm	Fr.R.	Continental: 8 mm
	Re.L.	Kleber: 5 mm	Re.R.	Kleber: 5 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT 3762,42

Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 441,84



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete)

350,16



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), LI - Repair and paint (partial)

250,00



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

478,02



Sill outer L, Scratch(es), LI - Repair and paint (complete)

372,60



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

396,60



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete)

350,16



Wing F L, Scratch(es), 67 - Polish

50,00



Door F L, Scratch(es), LI - Repair and paint (complete)

382,02



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

406,02

