



## CITROEN DS5: 1GAA479

Vinnumber:	<b>VF7KFRHC8DS508993</b>	Versionname:	<b>DS5 BER Hybrid4 Bus.GPS Plus 163PK Aut.</b>
First Registrationdate:	<b>3/12/2013</b>	Fiscalpower:	
Expertise Mileage:	<b>38669</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Hatchback</b>	Body color:	<b>Black</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Hybrid Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>3403</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

## Options

Radio CD		Seats electric F L	
Windows electric F		Seats electric F R	
Windows electric R		Panoramic roof	
Cruise Control		Central consol F	
Steering wheel multifunctional		Luggage cover	
Seats F heated		Front parking sensors	
Radio multimedia		Rear parking sensors	
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining leather</b>		
Type of climate control	<b>Autom climate control</b>		

## Limited Technical Inspection

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

## Degree of wear

	<b>225/50/17/98 V LightMetal</b>			
Summer tyres:	Fr.L.	<b>Michelin: 4 mm</b>	Fr.R.	<b>Michelin: 4 mm</b>
	Re.L.	<b>Michelin: 5 mm</b>	Re.R.	<b>Michelin: 5 mm</b>

## Assistance equipment

Repair kit	<b>Yes</b>	Compressor	<b>Yes</b>
Total cost ex VAT			<b>0,00</b>
Bumper F, Scratch(es), LI - Repair and paint (complete)			<b>0,00</b>



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

0,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

0,00



Tyre F R, Tear, E - Replace

0,00




Outer door handle F L, Scratch(es), LI - Repair and paint (complete)

0,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim R R, Scratch(es), LI - Repair and paint (complete)

0,00



Door R R, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

0,00



Wing R R, Scratch(es), LI - Repair and paint (complete)

0,00



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

0,00



Sill outer L, Scratch(es), LI - Repair and paint (complete)

0,00



Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

0,00

