



AUDI A1 SPORTBACK: 1RAJ583

Vinnumber:	WAUZZZ8X0HB036058	Versionname:	1.4 TDI 66kW
First Registrationdate:	26/10/2016	Fiscalpower:	
Expertise Mileage:	42432	Power Kw:	66
Bodytype:		Body color:	Dark Blue
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	4514
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Luggage cover	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

185/60/15/84 H LightMetal				
Summer tyres:	Fr.L.	Michelin: 5 mm	Fr.R.	Michelin: 5 mm
	Re.L.	Michelin: 6 mm	Re.R.	Michelin: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
		Jack	Yes

Total cost ex VAT	1168,16
Roof, Chemical polution, LI - Repair and paint (complete)	385,20



Wing R L, Chemical polution, LI - Repair and paint (complete)

246,56



Bonnet, Chemical polution, LI - Repair and paint (complete)

232,06



Alloy rim F R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R R, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Scratch(es), Acceptable

0,00

No pictures to display

Door F R, Dent(s), PDR - Paintless dent repair

63,00



Tailgate, Chemical polution, LI - Repair and paint (complete)

241,34

