



BMW 5: 1HLG058

Vinnumber:	WBA5N41050D873021	Versionname:	5 GRAN TURISMO 530da 211PK Aut.
First Registrationdate:	19/08/2014	Fiscalpower:	
Expertise Mileage:	114748	Power Kw:	155
Bodytype:		Body color:	Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	3714
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	HD	Seats electric F R	
GPS storage		Sun Roof electric	
Windows electric F		Panoramic roof	
Windows electric R		Central consol F	
Cruise Control		Luggage cover	
Steering wheel multifunctional		Front parking sensors	
Seats F heated		Rear parking sensors	
Radio multimedia		Type of Tow bar	No Tow bar
Type of headlighting	Headlighting LED		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Head-up Display			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

245/40/20/99 V LightMetal				
Winter tyres:	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Pirelli: 6 mm	Re.R.	Pirelli: 6 mm

Assistance equipment

Runflat	Yes
---------	------------

Total cost ex VAT	959,21
-------------------	---------------

Alloy rim R R, Scratch(es), LI - Repair and paint (complete)	95,00
--	--------------



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Bumper F R, Scratch(es), It - Spot repair

115,56



Bonnet, Chemical polution, LI - Repair and paint (complete)

348,09



Alloy rim R L, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim F L, Scratch(es), LI - Repair and paint (complete)

95,00



Interior, Dirty, Cleaning

0,00



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56

