



AUDI A3: 1KRT274			
Vinnumber:	WAUZZZ8V4FA180004	Versionname:	1.6 TDI 81KW ATTRACTION
First Registrationdate:	18/06/2015	Fiscalpower:	
Expertise Mileage:	209284	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metallic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	3815
Number of doors:	3		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Steering wheel multifunctional		Rear parking sensors	
Seats F heated		Type of Tow bar	Tow bar removable
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
Winter tyres:	205/55/16/91 H LightMetal			
	Fr.L.	Semperit: 8 mm	Fr.R.	Semperit: 8 mm
	Re.L.	Goodyear: 5 mm	Re.R.	Goodyear: 5 mm

Assistance equipment			
Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1302,88
Rearlight R taigate, Scratch(es), E - Replace			104,00



Alloy rim F R, Scratch(es), Acceptable			0,00
--	--	--	-------------

Wing R L, Scratch(es), LI - Repair and paint (complete) 308,20



Covering interior front pillar L, Burned, Acceptable 0,00

No pictures to display

Floor covering R, Stain, Chemical cleaning 0,00

No pictures to display

Wing R R, Scratch(es), Acceptable 0,00

No pictures to display

Grill, Scratch(es), Acceptable 0,00

No pictures to display

Boot carpet, Stain, Acceptable 0,00

No pictures to display

Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper F, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim R R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper R, Scratch(es), Acceptable 0,00

No pictures to display

Tailgate, Dent(s) and scratch(es), LI - Repair and paint (complete) 301,68



Alloy rim R L, Scratch(es), LI - Repair and paint (complete) 95,00



Ceiling, Hole, E - Replace 494,00



Trunk lid covering R, Scratch(es), Acceptable 0,00

No pictures to display

Bonnet, Chemical pollution, Acceptable 0,00

No pictures to display