



BMW 1: NA4500			
Vinnumber:	WBA1C110X0J836650	Versionname:	1 BER HATCH 118dA 143PK Aut.
First Registrationdate:	25/11/2014	Fiscalpower:	
Expertise Mileage:	83445	Power Kw:	105
Bodytype:		Body color:	Dark Grey
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	2633
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options			
Radio CD		Central consol F	
Windows electric F		Luggage cover	
Windows electric R		Front parking sensors	
Cruise Control		Rear parking sensors	
Steering wheel multifunctional		Type of Tow bar	No Tow bar
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection			
Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear				
225/45/17/91 W LightMetal				
Summer tyres:	Fr.L.	Continental: 4 mm	Fr.R.	Continental: 4 mm
	Re.L.	Continental: 4 mm	Re.R.	Continental: 4 mm

Assistance equipment	
Total cost ex VAT	1246,58
Door F R, Scratch(es), Acceptable	0,00
<i>No pictures to display</i>	
Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete)	95,00



Tailgate, Bad repair, Acceptable 0,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 385,08



Roof, Chemical polution, LI - Repair and paint (complete) 481,50



Bumper R, Bad repair, Acceptable 0,00



Door R R, Scratch(es), Acceptable 0,00

No pictures to display

Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete) 95,00

