



AUDI A3: 1HNU894

Vinnumber:	WAUZZZ8V3FA021636	Versionname:	A3 SB Attraction 110PK
First Registrationdate:	1/09/2014	Fiscalpower:	
Expertise Mileage:	104638	Power Kw:	81
Bodytype:		Body color:	Black
Gearbox:	MAN 6 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Battery functioning:	Yes	Parking lot:	4329
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Central consol F	
GPS storage	SD	Luggage cover	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

205/55/16/91 V LightMetal				
Summer tyres:	Fr.L.	Michelin: 2 mm	Fr.R.	Michelin: 2 mm
	Re.L.	Michelin: 0 mm	Re.R.	Michelin: 0 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
Total cost ex VAT			1328,62
Tailgate, Scratch(es), 67 - Polish			0,00
<i>No pictures to display</i>			
Headlight R, Broken, E - Replace			396,00



Wing F R, Dent(s) and scratch(es), LI - Repair and paint (complete)

220,18



Alloy rim F R, Scratch(es), LI - Repair and paint (complete)

95,00



Alloy rim R R, Scratch(es), Acceptable

0,00

No pictures to display

Wing R L, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper F R, Scratch(es), It - Spot repair

115,56



Bonnet, Chemical pollution, LI - Repair and paint (complete)

290,08



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Roof pillar L, Scratch(es), 67 - Polish

0,00

No pictures to display

Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80

