



BMW 3 BERLINE: HL8043

| | | | |
|------------------------------------|--------------------------|--------------|--------------------------------|
| Vinnumber: | WBA8F910X0K439695 | Versionname: | 2.0 316D (85KW) BERLINE |
| First Registrationdate: | 23/09/2015 | Fiscalpower: | |
| Expertise Mileage: | 57658 | Power Kw: | 85 |
| Bodytype: | Berline | Body color: | Dark Grey |
| Gearbox: | MAN 6 VIT | Paint type: | Metalic |
| Transmission: | Back | Rims summer: | Aluminium |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 2333 |
| Number of doors: | 4 | | |
| Number of seats: | 5 | | |
| Number head rests: | 5 | | |
| Rims summer: | Aluminium | | |
| Category: | Passenger Car | | |
| Oil level: | OK | | |
| Registration Certificate Car (BE): | Yes | | |

Options

| | |
|--------------------------------|------------------------------|
| Radio CD | Central consol F |
| Windows electric F | Rear parking sensors |
| Windows electric R | Type of Tow bar |
| Cruise Control | No Tow bar |
| Steering wheel multifunctional | |
| Radio multimedia | |
| Type of headlighting | Headlighting Halogen |
| Type of GPS | GPS big screen color |
| Type of Lining | Lining fabrics |
| Type of climate control | Autom climate control |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|---------------|----------------------------------|-----------------------|-------|-----------------------|
| | 205/60/16/92 W LightMetal | | | |
| Summer tyres: | Fr.L. | Goodyear: 5 mm | Fr.R. | Goodyear: 5 mm |
| | Re.L. | Goodyear: 4 mm | Re.R. | Goodyear: 4 mm |

Assistance equipment

| | | | |
|------------|------------|------------|------------|
| Repair kit | Yes | Compressor | Yes |
|------------|------------|------------|------------|

| | |
|-----------------------------------|------|
| Total cost ex VAT | 0,00 |
| Bumper F, Scratch(es), Acceptable | 0,00 |
| <i>No pictures to display</i> | |
| Bumper R, Scratch(es), Acceptable | 0,00 |

No pictures to display