



**BMW 2 ACTIVE TOURER: 1NFU284**

|                                    |                          |              |                               |
|------------------------------------|--------------------------|--------------|-------------------------------|
| Vinnumber:                         | <b>WBA2B310X0V693470</b> | Versionname: | <b>1.5 216D ACTIVE TOURER</b> |
| First Registrationdate:            | <b>15/02/2016</b>        | Fiscalpower: |                               |
| Expertise Mileage:                 | <b>171723</b>            | Power Kw:    | <b>85</b>                     |
| Bodytype:                          |                          | Body color:  | <b>Dark Grey</b>              |
| Gearbox:                           | <b>MAN 6 VIT</b>         | Paint type:  | <b>Metalic</b>                |
| Transmission:                      | <b>Front</b>             | Rims summer: | <b>Aluminium</b>              |
| Fueltype:                          | <b>Diesel</b>            | Oil level:   | <b>OK</b>                     |
| Battery functioning:               | <b>Yes</b>               | Parking lot: | <b>2226</b>                   |
| Number of doors:                   | <b>5</b>                 |              |                               |
| Number of seats:                   | <b>5</b>                 |              |                               |
| Number head rests:                 | <b>5</b>                 |              |                               |
| Rims summer:                       | <b>Aluminium</b>         |              |                               |
| Category:                          | <b>Passenger Car</b>     |              |                               |
| Oil level:                         | <b>OK</b>                |              |                               |
| Registration Certificate Car (BE): | <b>Yes</b>               |              |                               |

**Options**

|                                |                               |
|--------------------------------|-------------------------------|
| Radio CD                       | Central consol F              |
| Windows electric F             | Luggage cover                 |
| Windows electric R             | Type of Tow bar               |
| Steering wheel multifunctional | <b>No Tow bar</b>             |
| Radio multimedia               |                               |
| Type of headlighting           | <b>Headlighting Halogen</b>   |
| Type of GPS                    | <b>GPS big screen color</b>   |
| Type of Lining                 | <b>Lining fabrics</b>         |
| Type of climate control        | <b>Manual climate control</b> |

**Limited Technical Inspection**

|                     |           |                     |            |
|---------------------|-----------|---------------------|------------|
| Airco functioning   | <b>OK</b> | Battery functioning | <b>Yes</b> |
| Tires wear profile  | <b>OK</b> | Power steering      | <b>Yes</b> |
| Idle position       | <b>OK</b> | Sound engine        | <b>OK</b>  |
| Engine startingtime | <b>OK</b> | Clutch test         | <b>OK</b>  |
| Exhaust gass        | <b>OK</b> | Wiper fluid level   | <b>OK</b>  |
| Handbrake           | <b>OK</b> | Transmission        | <b>OK</b>  |
|                     |           | Lighting            | <b>OK</b>  |
|                     |           | Wiperblades         | <b>OK</b>  |

**Degree of wear**

|                                  |       |                       |       |                       |
|----------------------------------|-------|-----------------------|-------|-----------------------|
| <b>205/60/16/92 W LightMetal</b> |       |                       |       |                       |
| Summer tyres:                    | Fr.L. | <b>Michelin: 3 mm</b> | Fr.R. | <b>Michelin: 3 mm</b> |
|                                  | Re.L. | <b>Hankook: 4 mm</b>  | Re.R. | <b>Hankook: 4 mm</b>  |

**Assistance equipment**

|   |        |
|---|--------|
| Total cost ex VAT   | 274,80 |
| Bumper R, Scratch(es), Acceptable                                   | 0,00   |
| <i>No pictures to display</i>                                       |        |
| Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) | 211,80 |



|  |      |
|--|------|
| Alloy rim F R, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*

|  |       |
|--|-------|
| Wing R R, Dent(s), PDR - Paintless dent repair | 63,00 |
|--|-------|



|  |      |
|--|------|
| Alloy rim R R, Scratch(es), Acceptable | 0,00 |
|--|------|

*No pictures to display*