



**FIAT DUCATO: 1PSS776**

Vinnumber:	<b>ZFA2500002B76919</b>	Versionname:	
First Registrationdate:	<b>8/09/2016</b>	Fiscalpower:	
Expertise Mileage:	<b>271513</b>	Power Kw:	<b>109</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>LCV04</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>No</b>		

**Options**

Radio CD	Type of Tow bar	<b>No Tow bar</b>
Windows electric F		
Cruise Control		
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining artificial leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/16/115 R Steel</b>				
Summer tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 4 mm</b>	Re.R.	<b>Bridgestone: 4 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Jack	<b>Yes</b>
-------------	-----------	------	------------

Total cost ex VAT	2209,32
Supplementary brake lights, Broken, E - Replace	64,00



No pictures to display

Bumper R, Hole, E - Replace

329,40



Wheel arch cover R R, Scratch(es), E - Replace

64,00



Registration Document, Missing, E - Replace

150,00

No pictures to display

Trunk door R L, Dent(s), Acceptable

0,00

No pictures to display

Door F R, Dent(s) and scratch(es), Le - Replace and paint

847,88




Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

217,56



Spare wheel, Missing, E - Replace

153,60

