



**KIA Carens: 1GTQ163**

Vinnumber:	<b>KNAHT815AE7070057</b>	Versionname:	<b>CARENS Business Line ISG 115PK</b>
First Registrationdate:	<b>25/04/2014</b>	Fiscalpower:	
Expertise Mileage:	<b>136177</b>	Power Kw:	<b>85</b>
Bodytype:		Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Metalic</b>
Transmission:	<b>Front</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>1424</b>
Number of doors:	<b>5</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Passenger Car</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Central consol F	
Windows electric F	Luggage cover	
Windows electric R	Rear parking sensors	
Cruise Control	Type of Tow bar	<b>No Tow bar</b>
Steering wheel multifunctional		
Radio multimedia		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>GPS big screen color</b>	
Type of Lining	<b>Lining fabrics</b>	
Type of climate control	<b>Autom climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**










	<b>205/55/16/92 V Steel</b>			
Winter tyres:	Fr.L.	<b>Bridgestone: 4 mm</b>	Fr.R.	<b>Bridgestone: 4 mm</b>
	Re.L.	<b>Bridgestone: 5 mm</b>	Re.R.	<b>Bridgestone: 5 mm</b>

**Assistance equipment**

Emergency spare wheel	<b>Yes</b>	Jack	<b>Yes</b>
-----------------------	------------	------	------------

Total cost ex VAT	<b>903,70</b>
Bonnet, Dent(s), PDR - Paintless dent repair	<b>63,00</b>



Sill outer L, Scratch(es), LI - Repair and paint (complete)	0,00
	
Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
	
Bodywork, Not original part, Acceptable	0,00
No pictures to display	
Door F R, Scratch(es), LI - Repair and paint (complete)	318,35
	
Wing F R, Scratch(es), Acceptable	0,00
No pictures to display	
Wheel cover F L, Scratch(es), E - Replace	30,00
	
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)	0,00
	
Wheel cover R R, Scratch(es), E - Replace	30,00
	
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35
	
Wheel cover F R, Scratch(es), E - Replace	30,00
	
Wing R R, Scratch(es), LI - Repair and paint (complete)	0,00
	
Bumper F, Dent(s) and scratch(es), Le - Replace and paint	0,00



Wheel cover R L, Scratch(es), E - Replace 30,00



Rearview mirror housing L, Broken, E - Replace 84,00



Bumper R, Scratch(es), Acceptable 0,00

*No pictures to display*