



MERCEDES C: 1HRT431

Vinnumber:	WDD2050041F081839	Versionname:	C BER 220 BlueTEC 163PK
First Registrationdate:	16/09/2014	Fiscalpower:	
Expertise Mileage:	164734	Power Kw:	120
Bodytype:	Berline	Body color:	Black
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Back	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2402
Maintenance:	SERV B3 51 DAGEN GEPASSEERD		
Battery functioning:	Yes		
Number of doors:	4		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Front parking sensors	
GPS storage		Rear parking sensors	
Windows electric F		Type of Tow bar	Tow bar removable
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/45/18/95 Y LightMetal				
Summer tyres:	Fr.L.	Bridgestone: 4 mm	Fr.R.	Bridgestone: 4 mm
	Re.L.	Firestone: 6 mm	Re.R.	Firestone: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	793,35
-------------------	---------------

Tyre F L, Worn, Acceptable	0,00
----------------------------	-------------



Alloy rim R L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Alloy rim R R polished, Scratch(es), LI - Repair and paint (complete) 95,00



Bonnet, Chemical polution, 67 - Polish 0,00



Tyre F R, Worn, Acceptable 0,00



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete) 95,00



Outer valance R, Missing, E - Replace 95,00



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Dent(s), Acceptable 0,00

No pictures to display

Maintenance, Maintenance, Execute 0,00



Door R R, Bad repair, LI - Repair and paint (complete) 318,35



Bumper F L, Scratch(es), Acceptable	0,00
-------------------------------------	------

No pictures to display

Alloy rim F R polished, Scratch(es), LI - Repair and paint (complete)	95,00
---	-------

