



PEUGEOT PARTNER TEPEE: 1KEN190

Vinnumber:	VF37J9HL0FJ612132	Versionname:	1.6 HDI 84KW TEPEE ACTIVE
First Registrationdate:	15/04/2015	Fiscalpower:	
Expertise Mileage:	193983	Power Kw:	84
Bodytype:		Body color	White
Gearbox:	MAN 5 VIT	Paint type	Opaque
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	2611
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Manual climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	NOT OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/65/15/94 H Steel			
	Fr.L.	Michelin: 1 mm	Fr.R.	Michelin: 1 mm
	Re.L.	Michelin: 3 mm	Re.R.	Michelin: 3 mm

Assistance equipment

Spare wheel	Yes	Jack	Yes
-------------	------------	------	------------

Total cost ex VAT	1556,58
-------------------	----------------

Tailgate handle, Broken, E - Replace	60,00
--------------------------------------	--------------



Door F R, Scratch(es), LI - Repair and paint (complete)

318,35



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)	308,20
---	--------



Sill outer L, Scratch(es), Acceptable	0,00
---------------------------------------	------

No pictures to display

Sliding door R, Scratch(es), LI - Repair and paint (complete)	318,35
---	--------



Bonnet, Bad repair, Acceptable	0,00
--------------------------------	------



Boot carpet, Waterinfiltration, E - Replace	100,00
---	--------



Headlight R, Waterinfiltration, Acceptable	0,00
--	------

No pictures to display

Certificate Of Conformity, Missing, E - Replace	150,00
---	--------

No pictures to display

Tailgate, Dent(s), LI - Repair and paint (complete)	301,68
---	--------

