



MAZDA CX-5: 1HXX376

Vinnumber:	JMZKEF91800320226	Versionname:	CX-5 4x2 Sense 150PK Aut.
First Registrationdate:	24/10/2014	Fiscalpower:	
Expertise Mileage:	97909	Power Kw:	110
Bodytype:	SUV	Body color:	Dark Blue
Gearbox:	Automatic	Paint type:	Metalic
Transmission:	Front	Rims summer:	Aluminium
Fueltype:	Diesel	Oil level:	OK
Maintenance:	NOT OK	Parking lot:	2720
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Aluminium		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

Radio CD		Central consol F	
GPS storage	HD	Luggage cover	
GPS storage		Front parking sensors	
Windows electric F		Rear parking sensors	
Windows electric R		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

225/65/17/102 V LightMetal				
Summer tyres:	Fr.L.	Yokohama: 4 mm	Fr.R.	Yokohama: 4 mm
	Re.L.	Yokohama: 7 mm	Re.R.	Yokohama: 7 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	------------	------------	------------

Total cost ex VAT	115,56
-------------------	---------------

Bumper corner R L, Scratch(es), Acceptable	0,00
--	-------------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	-------------



Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56

