



**MERCEDES SPRINTER: 1HXS688**

Vinnnummer:	<b>WDB90663315942647</b>	Versionname:	
First Registrationdate:		Fiscalpower:	
Expertise Mileage:	<b>360555</b>	Power Kw:	<b>120</b>
Bodytype:	<b>Transporter</b>	Body color:	<b>White</b>
Gearbox:	<b>MAN 6 VIT</b>	Paint type:	<b>Opaque</b>
Transmission:	<b>Back</b>	Rims summer:	<b>Steel</b>
Fueltype:	<b>Diesel</b>	Oil level:	<b>OK</b>
Maintenance:	<b>OK</b>	Parking lot:	<b>LCV06</b>
Battery functioning:	<b>Yes</b>		
Number of doors:	<b>5</b>		
Number of seats:	<b>3</b>		
Number head rests:	<b>3</b>		
Rims summer:	<b>Steel</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

GPS storage	<b>SD</b>	Central consol F	
Windows electric F		Type of Tow bar	<b>No Tow bar</b>
Cruise Control			
Radio multimedia			
Type of headlighting	<b>Headlighting Halogen</b>		
Type of GPS	<b>GPS big screen color</b>		
Type of Lining	<b>Lining fabrics</b>		
Type of climate control	<b>Manual climate control</b>		

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>235/65/16/115 R Steel</b>				
Summer tyres:	Fr.L.	<b>Michelin: 6 mm</b>	Fr.R.	<b>Michelin: 6 mm</b>
	Re.L.	<b>Michelin: 6 mm</b>	Re.R.	<b>Michelin: 6 mm</b>

**Assistance equipment**

Spare wheel	<b>No</b>	Compressor	<b>No</b>
Emergency spare wheel	<b>No</b>	Jack	<b>Yes</b>
Repair kit	<b>No</b>	Runflat	<b>No</b>

Total cost ex VAT 3399,29

Engine, Maintenance, P - Check 0,00



Sliding door R, Dent(s) and scratch(es), LI - Repair and paint (complete)

382,02



Door F R, Dent(s), Acceptable

0,00

No pictures to display

SD card, Missing, E - Replace

206,25



Wing R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15



Bumper F, Missing, E - Replace

84,00



Spare wheel, Missing, E - Replace

153,60



Wing R R, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete)

217,56





Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 238,76



Bumper R, Dent(s) and scratch(es), E - Replace 329,40



Grill, Scratch(es), LI - Repair and paint (partial) 100,00



Ignition key, Missing, E - Replace 150,00



Grill frame, Broken, E - Replace 99,00



Trunk door R R, Dent(s) and scratch(es), LI - Repair and paint (complete) 334,76



Rearlight L, Scratch(es), 67 - Polish 0,00



Sidewall mid L (LCV) ; Rust, LI - Repair and paint (complete) 231,15





Trunk door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

334,76



Sill outer R, Dent(s) and scratch(es), LI - Repair and paint (complete)

232,88



Rearview mirror housing R, Broken, E - Replace

74,00

