



PEUGEOT 2008; 1HHU076

Vinnumber:	VF3CU8HR0EY006447	Versionname:	2008 Active 68PK
First Registrationdate:	28/07/2014	Fiscalpower:	
Expertise Mileage:	111615	Power Kw:	50
Bodytype:	Break	Body color:	Grey
Gearbox:	MAN 5 VIT	Paint type:	Metalic
Transmission:	Front	Rims summer:	Steel
Fueltype:	Diesel	Oil level:	OK
Maintenance:	OK	Parking lot:	2208
Battery functioning:	Yes		
Number of doors:	5		
Number of seats:	5		
Number head rests:	5		
Rims summer:	Steel		
Category:	Passenger Car		
Oil level:	OK		
Registration Certificate Car (BE):	Yes		

Options

GPS storage		Luggage cover	
GPS storage	HD	Rear parking sensors	
Windows electric F		Type of Tow bar	No Tow bar
Cruise Control			
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/60/16/89 M-S Steel			
Summer tyres:	Fr.L.	Bridgestone: 7 mm	Fr.R.	Bridgestone: 7 mm
	Re.L.	Pirelli: 7 mm	Re.R.	Pirelli: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	2016,80
Door F L, Scratch(es), LI - Repair and paint (complete)	318,35



Rocker panel inner F L, Scratch(es), Forfeit 115,56



Door F R, Dent(s) and scratch(es), LI - Repair and paint (complete) 318,35



Wheel cover F L, Scratch(es), Acceptable 0,00

No pictures to display

Dashboard, Scratch(es), Smart repair 110,64



Wheel cover F R, Scratch(es), Acceptable 0,00

No pictures to display

Bumper corner R R, Dent(s), Smart repair 110,64



Wheel cover R L, Scratch(es), Acceptable 0,00

No pictures to display

Rear window, Scratch(es), E - Replace 370,00



Bumper F L, Scratch(es), Acceptable 0,00

No pictures to display

Door R L, Dent(s), PDR - Paintless dent repair 63,00



Bonnet, Chemical polution, LI - Repair and paint (complete) 290,08



Interior, Dirty, Cleaning 100,00



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete) 220,18

