



MERCEDES Vito: 1CWW392

| | | | |
|-------------------------|---------------------------------|--------------|------------------------------|
| Vinnumber: | WDF63960113723211 | Versionname: | VITO 110 B/F SWB 95PK |
| First Registrationdate: | 15/03/2012 | Fiscalpower: | |
| Expertise Mileage: | 170939 | Power Kw: | 70 |
| Bodytype: | Transporter | Body color: | Red |
| Gearbox: | MAN 6 VIT | Paint type: | Opaque |
| Transmission: | Front | Rims summer: | Steel |
| Fueltype: | Diesel | Oil level: | OK |
| Battery functioning: | Yes | Parking lot: | 3825 |
| Number of doors: | 4 | | |
| Number of seats: | 3 | | |
| Number head rests: | 3 | | |
| Rims summer: | Steel | | |
| Category: | Light Commercial Vehicle | | |
| Oil level: | OK | | |

Options

| | | | |
|-------------------------|-------------------------------|----------------------|-------------------|
| Radio CD | | Rear parking sensors | |
| Windows electric F | | Type of Tow bar | No Tow bar |
| Type of headlighting | Headlighting Halogen | | |
| Type of Lining | Lining fabrics | | |
| Type of climate control | Manual climate control | | |

Limited Technical Inspection

| | | | |
|---------------------|-----------|---------------------|------------|
| Airco functioning | OK | Battery functioning | Yes |
| Tires wear profile | OK | Power steering | Yes |
| Idle position | OK | Sound engine | OK |
| Engine startingtime | OK | Clutch test | OK |
| Exhaust gass | OK | Wiper fluid level | OK |
| Handbrake | OK | Transmission | OK |
| | | Lighting | OK |
| | | Wiperblades | OK |

Degree of wear

| | | | | |
|------------------------------|-------|------------------------|-------|------------------------|
| 195/65/16/102 T Steel | | | | |
| Summer tyres: | Fr.L. | Firestone: 5 mm | Fr.R. | Firestone: 5 mm |
| | Re.L. | Firestone: 5 mm | Re.R. | Firestone: 5 mm |

Assistance equipment

| | | | |
|-------------|------------|------|------------|
| Spare wheel | Yes | Jack | Yes |
|-------------|------------|------|------------|

| | |
|---|---------------|
| Total cost ex VAT | 450,44 |
| Bonnet, Dent(s) and scratch(es), LI - Repair and paint (complete) | 217,56 |



| | |
|---|-------------|
| Bodywork, Not original part, Acceptable | 0,00 |
|---|-------------|

No pictures to display

| | |
|--|---------------|
| Sill outer R, Rust, LI - Repair and paint (complete) | 232,88 |
|--|---------------|

