



**DODGE RAM: 1AZN050**

Vinnumber:	<b>3D7TT2CT2AG165282</b>	Versionname:	
First Registrationdate:	<b>1/07/2010</b>	Fiscalpower:	
Expertise Mileage:	<b>66638</b>	Power Kw:	<b>291</b>
Bodytype:	<b>Off-road</b>	Body color:	<b>Grey</b>
Gearbox:	<b>Automatic</b>	Paint type:	<b>Metalic</b>
Transmission:		Rims summer:	<b>Aluminium</b>
Fueltype:	<b>Petrol</b>	Oil level:	<b>OK</b>
Battery functioning:	<b>Yes</b>	Parking lot:	<b>TRU17</b>
Number of doors:	<b>4</b>		
Number of seats:	<b>5</b>		
Number head rests:	<b>5</b>		
Rims summer:	<b>Aluminium</b>		
Category:	<b>Light Commercial Vehicle</b>		
Oil level:	<b>OK</b>		
Registration Certificate Car (BE):	<b>Yes</b>		

**Options**

Radio CD	Seats electric F L	
Windows electric F	Type of Tow bar	<b>Tow bar removable</b>
Windows electric R		
Cruise Control		
Steering wheel multifunctional		
Type of headlighting	<b>Headlighting Halogen</b>	
Type of GPS	<b>No GPS</b>	
Type of Lining	<b>Lining leather</b>	
Type of climate control	<b>Manual climate control</b>	

**Limited Technical Inspection**

Airco functioning	<b>OK</b>	Battery functioning	<b>Yes</b>
Tires wear profile	<b>OK</b>	Power steering	<b>Yes</b>
Idle position	<b>OK</b>	Sound engine	<b>OK</b>
Engine startingtime	<b>OK</b>	Clutch test	<b>OK</b>
Exhaust gass	<b>OK</b>	Wiper fluid level	<b>OK</b>
Handbrake	<b>OK</b>	Transmission	<b>OK</b>
		Lighting	<b>OK</b>
		Wiperblades	<b>OK</b>

**Degree of wear**

<b>295/65/22/129 S LightMetal</b>				
Summer tyres:	Fr.L.	<b>Toyo: 8 mm</b>	Fr.R.	<b>Toyo: 8 mm</b>
	Re.L.	<b>Toyo: 9 mm</b>	Re.R.	<b>Toyo: 9 mm</b>

**Assistance equipment**

Spare wheel	<b>Yes</b>
-------------	------------

Total cost ex VAT	1380,14
Rearlight R , Crack, E - Replace	91,50





Rearview mirror housing R, Broken, Le - Replace and paint 98,00



Ignition key, Missing, E - Replace 150,00

No pictures to display

Rearview mirror housing L, Scratch(es), Smart repair 110,64



Door F R, Scratch(es), Acceptable 0,00

No pictures to display

Wing R L, Scratch(es), LI - Repair and paint (complete) 231,15



Bumper R, Dent(s) and scratch(es), LI - Repair and paint (complete) 158,85



Bonnet, Stone chip(s), Acceptable 0,00

No pictures to display


Bumper F, Dent(s) and scratch(es), LI - Repair and paint (complete) 158,85



Maintenance book, Missing, E - Replace 0,00

No pictures to display

Interior, Dirty, Chemical cleaning 150,00



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

231,15

