


SKODA Octavia: 1HAU137

Vinnumber:	TMBJG7NE4E0229317	Versionname:	OCTAVIA COMBI Ambition 105PK
First Registrationdate:	5/06/2014	Fiscalpower:	
Expertise Mileage:	131945	Power Kw:	77
Bodytype:		Body color	Grey
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	OK	Parking lot	3125
Maintenance	IN 18200KM		
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage	SD	Luggage cover	
GPS storage		Type of Tow bar	No Tow bar
Windows electric F			
Windows electric R			
Cruise Control			
Steering wheel multifunctional			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	205/55/16/91 V Steel			
	Fr.L.	Bridgestone: 3 mm	Fr.R.	Bridgestone: 3 mm
	Re.L.	Bridgestone: 7 mm	Re.R.	Bridgestone: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			387,36
Rearview mirror housing R, Scratch(es), Acceptable			0,00
<i>No pictures to display</i>			
Bonnet, Stone chip(s), Acceptable			0,00
<i>No pictures to display</i>			
Wheel cover F R, Missing, E - Replace			30,00



Rearview mirror housing L, Scratch(es), LI - Repair and paint (complete)

115,56



Windscreen, Stone chip(s), Windscreen repair

0,00



Wing F R, Scratch(es), Acceptable

0,00

No pictures to display


Door frame R R, Scratch(es), Acceptable

0,00

No pictures to display

Rear window, Scratch(es), E - Replace

0,00



Wheel cover F L, Missing, E - Replace

30,00



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80

