


VOLKSWAGEN GOLF VII: 1LGG481

Vinnumber:	WVWZZZAUZFW336370	Versionname:	1.6 TDI 66KW TRENDLINE
First Registrationdate:	2/07/2015	Fiscalpower:	
Expertise Mileage:	91885	Power Kw:	66
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3424
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Central consol F	
GPS storage		Luggage cover	
GPS storage	SD	Front parking sensors	
Windows electric F		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Radio multimedia			
Type of headlighting	Headlighting Halogen		
Type of GPS	GPS big screen color		
Type of Lining	Lining fabrics		
Type of climate control	Autom climate control		

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	NOT OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Continental: 1,6 mm	Fr.R.	Continental: 1,6 mm
	Re.L.	Continental: 5 mm	Re.R.	Continental: 5 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
-----------------------	------------	------	------------

Total cost ex VAT	531,50
Roof, Chemical polution, LI - Repair and paint (complete)	481,50



Bodywork, Scratch(es), 67 - Polish	0,00
------------------------------------	------

No pictures to display

Seat cover F L, Dirty, Cleaning	25,00
---------------------------------	-------



Door R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper F, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Bumper R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Door F L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Maintenance, Maintenance, Execute	0,00
-----------------------------------	------



Wing R L, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display

Seat cover F R, Dirty, Cleaning	25,00
---------------------------------	-------



Door R R, Scratch(es), Acceptable	0,00
-----------------------------------	------

No pictures to display