


VOLKSWAGEN Golf: 1H2H849

Vinnumber:	WVWZZZAUZFP033634	Versionname:	GOLF BER Trendline 105PK
First Registrationdate:	21/10/2014	Fiscalpower:	
Expertise Mileage:	117339	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	MAN 5 VIT	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Diesel	Oil level	OK
Battery functioning	Yes	Parking lot	3603
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

GPS storage	Central consol F
Windows electric F	Luggage cover
Cruise Control	Front parking sensors
Steering wheel multifunctional	Rear parking sensors
Seats F heated	Type of Tow bar
Radio multimedia	No Tow bar
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Autom climate control
Adaptive cruise control	
Sport seats	

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

	195/65/15/91 H Steel			
Summer tyres:	Fr.L.	Uniroyal: 3 mm	Fr.R.	Uniroyal: 3 mm
	Re.L.	Continental: 6 mm	Re.R.	Continental: 6 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			2704,63
Ignition key, Broken, E - Replace			150,00



Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Rear spoiler, Dent(s), LI - Repair and paint (complete)

115,56



Bumper R, Scratch(es), LI - Repair and paint (complete)

211,80



Door R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

318,35



Bonnet, Scratch(es), LI - Repair and paint (complete)

290,08



Door F L, Chemical pollution, LI - Repair and paint (complete)

318,35



Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)

308,20



Wing F L, Dent(s) and scratch(es), LI - Repair and paint (complete)

320,18

Wing R L, Dents and scratches, LI - Repair and paint (complete)		229,10
		
Wheel cover R R, Missing, E - Replace		30,00
		
Wing R L, Chemical polution, LI - Repair and paint (complete)		308,20
		
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)		115,56
		