



TOYOTA AYGO: RR7747

Vinnumber:	JTDKGNCE90N161700	Versionname:	1.0 VVT-I X-PLAY MMT
First Registrationdate:	29/04/2016	Fiscalpower:	
Expertise Mileage:	48394	Power Kw:	51
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Steel
Fueltype:	Petrol	Oil level	OK
Battery functioning	Yes	Parking lot	3310
Number of doors	5		
Number of seats	4		
Number head rests	2		
Rims summer	Steel		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD	Luggage cover
GPS storage	HD Type of Tow bar
GPS storage	No Tow bar
Windows electric F	
Steering wheel multifunctional	
Radio multimedia	
Type of headlighting	Headlighting Halogen
Type of GPS	GPS big screen color
Type of Lining	Lining fabrics
Type of climate control	Manual climate control

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear


185/60/15/77 H LightMetal			
Summer tyres:	Fr.L.	Continental: 3 mm	Fr.R.
	Re.L.	Continental: 6 mm	Re.R.
		Continental: 3 mm	Continental: 6 mm

Assistance equipment

Repair kit	Yes	Compressor	Yes
------------	-----	------------	-----

Total cost ex VAT	1488,66
Wing R R, Dent(s), PDR - Paintless dent repair	135,00



Bonnet, Chemical polution, LI - Repair and paint (complete)		232,06
 		
Interior, Dirty, Cleaning		0,00
		
Bumper corner R R, Scratch(es), It - Spot repair		115,56
		
Ignition key, Missing, E - Replace		150,00
No pictures to display		
Door R L, Dent(s) and scratch(es), LI - Repair and paint (complete)		254,68
		
Door F L, Dent(s) and scratch(es), LI - Repair and paint (complete)		254,68
		
Wing R L, Scratch(es), It - Spot repair		115,56
		
Wheel covers (all), Scratch(es), E - Replace		0,00
		
Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)		115,56
		
Bumper F L, Scratch(es), It - Spot repair		115,56

