



VOLKSWAGEN GOLF VII: DM0602

Vinnumber:	WVWZZZAUZFP087179	Versionname:	1.6 TDI 77KW DSG 8MT HIGHLINE
First Registrationdate:	2/04/2015	Fiscalpower:	
Expertise Mileage:	70996	Power Kw:	77
Bodytype:		Body color	Black
Gearbox:	Automatic	Paint type	Metalic
Transmission:	Front	Rims summer	Aluminium
Fueltype:	Diesel	Oil level	OK
Maintenance	NOT OK	Parking lot	3328
Battery functioning	Yes		
Number of doors	5		
Number of seats	5		
Number head rests	5		
Rims summer	Aluminium		
Category	Passenger Car		
Oil level	OK		
Registration Certificate Car (BE)	Yes		

Options

Radio CD		Seats electric F L	
GPS storage	SD	Central consol F	
GPS storage		Luggage cover	
Windows electric F		Front parking sensors	
Windows electric R		Rear parking sensors	
Cruise Control		Type of Tow bar	No Tow bar
Steering wheel multifunctional			
Seats F heated			
Radio multimedia			
Type of headlighting	Headlighting Xenon		
Type of GPS	GPS big screen color		
Type of Lining	Lining leather		
Type of climate control	Autom climate control		
Adaptive cruise control			
Sport seats			

Limited Technical Inspection

Airco functioning	OK	Battery functioning	Yes
Tires wear profile	OK	Power steering	Yes
Idle position	OK	Sound engine	OK
Engine startingtime	OK	Clutch test	OK
Exhaust gass	OK	Wiper fluid level	OK
Handbrake	OK	Transmission	OK
		Lighting	OK
		Wiperblades	OK

Degree of wear

Summer tyres:	225/45/17/91 W LightMetal			
	Fr.L.	Pirelli: 5 mm	Fr.R.	Pirelli: 5 mm
	Re.L.	Continental: 7 mm	Re.R.	Continental: 7 mm

Assistance equipment

Emergency spare wheel	Yes	Jack	Yes
Total cost ex VAT			1288,80
Wing R R, Dent(s) and scratch(es), LI - Repair and paint (complete)			308,20



Bumper F, Scratch(es), LI - Repair and paint (complete)

211,80



Rear spoiler, Chemical polution, LI - Repair and paint (complete)

211,56



Door F R, Dent(s) and scratch(es), It - Spot repair

115,56



Alloy rim F L polished, Scratch(es), LI - Repair and paint (complete)

95,00



Wing R L, Scratch(es), Acceptable

0,00

No pictures to display

Bonnet, Stone chip(s), Acceptable

0,00

No pictures to display

Rearview mirror housing R, Scratch(es), LI - Repair and paint (complete)

115,56



Door R L, Scratch(es), Acceptable

0,00

No pictures to display

Bumper R, Scratch(es), Acceptable

0,00


No pictures to display

Maintenance, Maintenance, Execute

0,00



Door F L, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Door R R, Dent(s) and scratch(es), It - Spot repair	115,56
---	--------



Bonnet, Scratch(es), Acceptable	0,00
---------------------------------	------

No pictures to display